

Voss Clark - Defect Image - Original

Coil No.: 084220 (206494)	Printed: 12/15/2010 17:06
Inspected: 12/11/2010 03:20 - 12/11/2010 03:31	Inspection Location: Pickle

Defect Description	
Defect ID	8906
Class	LAO
Prod. Class / Test Class	NC / NC
Grade	---
Confidence	100 %
Dist. from DS	13.66 in
Dist. from OS	36.38 in
Distance from start	2145 ft 5.8 in
Width	1.890 in
Length	7.165 in
Period length	53.03 in
Period Id	21
Camera	4
Image ID	429
Coil Side	Bottom Side BF
Roll	-----

Coil Data:	
Coil No. :	
Material :	
Start :	12/11/10 03:20
Width :	52 inch
Length :	2287 ft
Defects :	7820
Customer Order #	4917588
Heat #	D02782
Mill ID #	
Mill Order #	ZX90237-001
Part #	A1HR006287
PO #	00508983
Rockwell	
Ship To	

\\CAMERA-PC01\images\00206494\04\P651003_00206494_04_srcimg_0429.tif

